



L7641

Product Features:

- Exterior: 100% nylon dobby check
- Interior: 100% polyester plush fleece
- Raglan sleeves
- Polyester/spandex binding on cuffs and hood
- Longer hem in back for extra coverage

Ladies' sizes: XS-4XL

Icons/Fabric Features:



Available Colours and PMS Colours

Textile fabric colours are subject to dye lot variation and will not be exact match to print pantone reference



Due to the nature of nylon, special care must be taken throughout the decoration process.

L7641- COAL HARBOUR® Kasey Ladies' Jacket

GARMENT MEASUREMENTS

| Size | XS | S | M | L | XL | 2XL | 3XL | 4XL |
|--|-----|---------|-----|---------|---------|---------|---------|---------|
| Chest - Half Measure | 18" | 19 1/2" | 21" | 22 1/2" | 24" | 25 1/2" | 27 1/2" | 29 1/2" |
| Chest - Full Measure | 36" | 39" | 42" | 45" | 48" | 51" | 55" | 59" |
| Body Length from HPS (At Front) | 25" | 25 1/2" | 26" | 26 1/2" | 27 1/2" | 28 1/2" | 29" | 29 1/2" |
| Body Length from HPS (At Back) | 26" | 26 1/2" | 27" | 27 1/2" | 28 1/2" | 29 1/2" | 30" | 30 1/2" |
| Sleeve Length-CB | 29" | 31" | 33" | 34" | 35" | 35 1/2" | 36" | 36 1/2" |

Finished measurements in inches. Refer to "How to Measure" guide for detailed information on measurement instructions.

LADIES' General Sizing Guide

| Size | XS | S | M | L | XL | 2XL | 3XL | 4XL |
|-------------------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|
| Numeric Size | 2 | 4-6 | 8-10 | 12-14 | 16 | 18-20 | 22 | 24 |
| Bust | 32"-34" | 35"-36" | 37"-38" | 39"-41" | 42"-44" | 45"-47" | 48"-51" | 52"-55" |
| Waist | 24"-25" | 26"-27" | 28"-30" | 30"-32" | 33"-35" | 36"-38" | 40"-42" | 42"-44" |
| Hip | 33"-35" | 35"-37" | 37"-39" | 39"-41" | 42"-44" | 45"-47" | 48"-50" | 50"-52" |
| Sleeve Length-CB | 30"-30 1/2" | 30 1/2"-31" | 31 1/2"-32" | 32 1/2"-33" | 33 1/2"-34" | 34"-34 1/2" | 34 1/2"-35" | 34 1/2"-35" |

COAL HARBOUR®

PRINTING INSTRUCTIONS FOR NYLON FABRICS

Due to the nature of Nylon fabric, special care must be taken throughout the decoration process. Special care must be taken during the decoration process and after.

Here are some tips to effectively decorate these products.

Heat Transfer/Screen Printing:

- Garment temperature must not exceed 310°F or 154°C.
- Use fast fashion/low cure temperature ink to help prevent the need for a higher temperature to cure the ink.
- A test sample run is recommended in all printing processes, especially if you have a large order or if your printer does not specialize in