

## DF7663 - DRYFRAME® Dry Tech Parka

### GARMENT MEASUREMENTS

Size	XS	S	M	L	XL	2XL	3XL	4XL
Chest - Half Measure	22 1/8"	23 5/8"	35 1/8"	26 5/8"	28 1/8"	29 5/8"	31 3/8"	33 5/8"
Chest - Full Measure	44 1/4"	47 1/4"	50 1/4"	53 1/4"	56 1/4"	58 1/4"	62 1/4"	66 1/4"
Body Length from HPS (At Front)	34 1/2"	35"	35 1/2"	36"	37"	38"	38 1/2"	39"
Sleeve Length-CB	35"	35 3/4"	36 1/2"	37 1/4"	38"	38 3/4"	39 1/2"	40 1/4"

*Finished measurements in inches. Refer to "How to Measure" guide for detailed information on measurement instructions.*

### ADULT General Sizing Guide

Size	XS	S	M	L	XL	2XL	3XL	4XL
Chest	30"-32"	34"-36"	38"-40"	42"-44"	46"-48"	50"-52"	54"-55"	56"-57"
Waist	26"-29"	29"-32"	32"-35"	35"-38"	38"-41"	41"-44"	44"-47"	47"-50"
Sleeve Length-CB	31"-32"	32"-33 1/2"	34"-35"	35"-36"	36"-37"	37"-38"	38"-39"	38 1/2"-39"



### PRINTING INSTRUCTIONS FOR NYLON FABRICS

**Due to the nature of Nylon fabric, special care must be taken throughout the decoration process. Special care must be taken during the decoration process and after.**

Here are some tips to effectively decorate these products.

#### Heat Transfer/Screen Printing:

- Garment temperature must not exceed 310°F or 154°C.
- Use fast fashion/low cure temperature ink to help prevent the need for a higher temperature to cure the ink.
- A test sample run is recommended in all printing processes, especially if you have a large order or if your printer does not specialize in printing on Nylon fabrics.